




report date: 2024-08-21

General information

Make	SEAT
Model	IBIZA Ibiza Sport
Colour	Yellow
Year of manufacture	2001
Top speed	117 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	145 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg





MOT history

MOT #17	2015-01-23 12:15
MOT test number	359683725046
Result	✓ Passed
Next expiry date	2016-01-24
Notice	Play in steering rack inner joint(s)
Advice	Nearside Front Lower Suspension arm slightly distorted (2.4.G.1)
Advice	Offside Front Ball joint has slight play (2.2.B.1f)
Notice	Oil leak
Advice	Offside Front Lower Suspension arm slightly distorted (2.4.G.1)

MOT #16	2015-01-23 12:15
MOT test number	446713525065
Result	✗ Failed
Advice	Nearside Front Lower Suspension arm slightly distorted (2.4.G.1)
Notice	Oil leak
Advice	Offside Front Ball joint has slight play (2.2.B.1f)
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)
Notice	Play in steering rack inner joint(s)
Advice	Offside Front Lower Suspension arm slightly distorted (2.4.G.1)

MOT #15	2014-01-20 17:17
MOT test number	207660124095
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)



MOT #14 2014-01-20 17:17

MOT test number 367570324087

Result ✗ Failed

- Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Nearside Front Registration plate lamp not working (1.1.C.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #13 2013-01-22 13:27

MOT test number 115662523467

Result ✓ Passed

MOT #12 2013-01-21 11:46

MOT test number 749601323090

Result ✗ Failed

- Fail** Offside Registration plate lamp not fitted (1.1.C.1b)
- Fail** Windscreen has a combination of minor damage areas which restrict the drivers view (8.3.1c)

MOT #11 2012-01-09 14:57

MOT test number 698379902003

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #10	2012-01-06 11:01
MOT test number	885976102004
Result	✗ Failed
Fail	Fuel cap/sealing device missing (7.2.4a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #9	2011-01-25 10:19
MOT test number	139315421436
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #8	2011-01-24 17:01
MOT test number	505974821001
Result	✗ Failed
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)
Fail	Driver's door cannot be opened from inside the vehicle (6.2.B.1b)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #7	2010-01-20 14:04
MOT test number	871210620090
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6	2010-01-20 10:38
MOT test number	111390020461
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Pass with rectification	Nearside Headlamp not in good working order adversely affecting beam image (1.2.4a)
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
Fail	Exhaust has a major leak of exhaust gases (7.1.2)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5	2008-12-31 13:00
MOT test number	533836268370
Result	✓ Passed

MOT #4	2008-12-31 13:00
MOT test number	162986568302
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.5c)
Pass with rectification	Offside Headlamp not in good working order adversely affecting beam image (1.2.4a)



MOT #3 2008-01-10 08:36

MOT test number 563300718078

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2007-01-02 09:49

MOT test number 974812807002

Result ✓ Passed

MOT #1 2006-01-24 13:52

MOT test number 471744526060

Result ✓ Passed




Damage history

Check the damage history for this SEAT. See if, where and when this SEAT had damage and the car repair costs. We also check if this SEAT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SEAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this SEAT? How many owners did this SEAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT

More info >

Plate changes

See in this check if this SEAT had different number plates.

Number of plates	1
Current registration	Y551BCG
Plate since	2024-08-21
Current registration	Y551BCG
Plate since	2024-08-21

More info >



Finance check

Check if this SEAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SEAT has been settled.

If not, and you buy this SEAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SEAT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2001-05-24
Last registration	2015-01-23
Complete history	See info



Registration #1	2001-05-24	6 mi
Registration #2	2006-01-24	17.190 mi
Registration #3	2007-01-02	28.602 mi
Registration #4	2008-01-10	44.965 mi
Registration #5	2008-12-31	56.948 mi
Registration #6	2010-01-20	67.581 mi
Registration #7	2010-01-20	76.581 mi
Registration #8	2011-01-24	74.387 mi
Registration #9	2012-01-24	74.387 mi
Registration #10	2013-01-24	74.387 mi
Registration #11	2014-01-24	74.387 mi
Registration #12	2015-01-24	74.387 mi
Registration #13	2016-01-24	74.387 mi
Registration #14	2017-01-24	74.387 mi
Registration #15	2018-01-24	74.387 mi

[More info >](#)



Car features

The SEAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete SEAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1640 mm
Height	1422 mm
Length	3876 mm
Wheel base	2443 mm
Kerb weight	1040 kg

Additional information

Number of doors	3
Number of seats	5
Number of axles	2